

Issue 1, 1984 : Datasette 1

Model: 1530, 1531

PROBLEM: External noise interferences cause a LOAD ERROR with some newer model datasettes. An engineering change has been issued; however, the possibility remains that some units have reached the field uncorrected. SOLUTION:

PCB Assy # CMR-001-0

1) REMOVE the 150pF cap at C4 and REPLACE with a Ceramic 470pF 50WV

2)ADD C9 across R17 and R18 PCB Assy# 017-5001-01

1) REMOVE the 150pF cap at C4 and REPLACE with a Ceramic 470pF 50wV


2)ADD C9 across R17 and R18 Note: use pins on

SW1 - resistors are printed type


PCB Assy # NP-090

1) Check C4 for 470pF cap

2)ADD C9 across R1 and R2



PCB Assy #: CMR-001-0 017-5001-01



CB Assy # NP-090

Note - Correct Values:

C4 Ceramic capacitor 470pF +/- 20% 50 Working Volts C9 Ceramic capacitor .0033uF +/- 20% 50 Working Volts