

ISSUE 12, 1985 : MONITOR 3



MODEL : 1701/1702/1802/CM 141/1902

© 1980 COMMODORE BUSINESS MACHINES INC

CQS CENTER MONITOR REPAIRS

All CQS centers are expected to perform component level repairs on Commodore Monitors. It is NOT FEASIBLE to EXCHANGE a board on a monitor. The time and work involved to remove a board from these products is far too involved to consider practical. The service policy for MONITOR REPAIRS is:

IN-WARRANTY - Labor Rate - \$23.50
Parts Reimbursement - Attach
receipt for parts purchase
to NARDA form (Written proof
required) OR Commodore part #

OUT-OF-WARRANTY - Component level repair at
consumer's expense

To assist you in the acquisition of Monitor parts, the Cross-Reference Manual will be updated to include monitor information as soon as possible.